

Phone: 673-2331730 Fax : 673-2331730 AFTN: WBSBYNYX Email : ais.brunei@civil-aviation.gov.bn	NEGARA BRUNEI DARUSSALAM AERONAUTICAL INFORMATION SERVICE DEPARTMENT OF CIVIL AVIATION BRUNEI INTERNATIONAL AIRPORT, BB2513	NOTAM SUMMARY 01/2016 01 JANUARY 2016
---	--	--

THE FOLLOWING NOTAM A/B SERIES WERE STILL IN FORCE AS OF 1601010001UTC. NOTAM NOT INCLUDED HAVE EITHER BEEN CANCELLED, TIME EXPIRED, SUPERSEDED BY AIP SUPPLEMENT OR INCORPORATED IN AIP.

LOCATION: BRUNEI (WBSB)		
NTM NR	DATE	TEXT
A/B0468	121113	EFF 1211150000/PERM Brunei Darussalam will only accept submission of FPL & ATS messages in new format filed in accordance with amendment 1 to the 15 th edition of PANS-ATM DOC 4444. FPL & ATS messages in present format will be rejected & as a consequence such flights will be delayed.
A/B0273	130910	EFF 1309102300/PERM All aircraft are advised to use new lead-in line for Stand 8.
A/B0279	130914	EFF 1309172300/PERM All aircraft are to used new lead-in line for Stand 5, 6 and 7.
A/B0296	130928	EFF 1309282200/PERM All aircraft advised to use new lead-in line for Stand 2.
A/B0387	131115	EFF 1311150615/PERM Stand 1 concourse and aerobridge is serviceable.
A/B0252	140726	EFF 1407260100/PERM All aircraft are advised to use new lead-in line for Stand 1.
A/B0433	151105	EFF 1511300000/1601310900 NDB "BR" freq 318Khz is not available due to installation of new equipment.
A/B0443	151112	Effective 1511120100/1602122359 RVR unserviceable.
A/B0535	151231	Effective 1512310345/1610312359 Presence of mobile crane, height 50m AMSL, within radius of 100m erected at 045817N 1145553E (Berakas Power Station, Kg Terunjing Baru). Remark/Crane marked with red and white chequered flag and lit at night.
A/B0538	151231	Effective 1512310645/1601312359 Aerodrome Fire fighting downgrade to Category 8.
A/B0539	151231	Effective 1512310900/1601310900 ILS LLZ 'BE' frequency 108.9Mhz no standby facilities.

LOCATION: ANDUKI (WBAK)		
NTM NR	DATE	TEXT
A/B0284	140901	Effective 1409010700/PERM The remote switch function for Aerodrome Ground Lighting (AGL) on freq 122.1Mhz is currently out of service due to installation of the new switchboard panel.
A/B0423	151103	Effective 1511030200/1602292359 Panaga Health Centre Helipad (PHC) position 043638.889N 1141804.931E closed.
A/B0486	151128	Effective 1511280001/1602282359 concentration of birds in the vicinity of the runway. Remark/Pilot to exercise caution during landing and take-off.
A/B0487	151128	Effective 1511280001/1603312359 Presence of yellow color weight with dimension about 24 ins by 24 ins within weight of 500lb loc at the side of entrance taxiway C.
A/B0489	151201	Effective 151201000/1605312359 Brunei Shell Petroleum Headquarters Helipad position 043630.296N 1141717.238E to exercise caution for pilot landing at night will be at own discretion due to limited lights at helipad.
A/B0501	151208	Effective 1512080530/1601072369 Presence of land rig T-203 with height of 200ft (60M), Well S937 at E-11. Position 043636.64N 1141731.16E. Lit at night.
A/B0506	151210	Effective 1512082230/1603012359 Presence of offshore barge, Maersk Completer with deck height of 150ft, derrick height 350ft at Danau (0450.69N 11433.64E). Lit at night.
A/B0507	151210	Effective 1512100001/1601312359 Kuala Belait helipad windsock lightings (043523.40N 1141106.043E) unserviceable.
A/B0517	151216	Effective 1512160320/1606162359 H24 West Castor on site Berangan-A with deck height 202ft ASL, position 044935.278N 1140205.778E.
A/B0525	151222	Effective 1512221350/1601312359 Rig Ensco 505 with derrick height of 314ft MSL position 053225N 1142215E. Lighted at night.
A/B0533	151230	Effective 1512300500/1601312359 Sequence flashing approach light (SFL) runway 23 unserviceable.
A/B0536	151231	Effective 1512312300/1601071100 Daily between 2300/1100 Brunei Shell Head Quarter Helipad (E10) position 043630.296N 1141717.238E closed due crane operation height 60ft high in the vicinity of Well S-723. Lit at night.
A/B0537	151231	Effective 1512302300/1601031100 Daily between 2300/1100 Wireline activity (Well S-415) with crane operations approximate height of 60ft position at left base runway 05 (E-31) 04383.89N 1142155.17E

LATEST AIP AMENDMENT ISSUED : 01/14 dated 12 Dec 2014

LATEST AIC ISSUED : 02/15 dated 07 Dec 2015

CURRENT AIP SUPPLEMENTS : 01/01 dated 20 Sept 2001
02/01 dated 01 Nov 2001
02/09 dated 25 July 2009
07/09 dated 01 Oct 2009
04/10 dated 14 Sept 2010
01/13 dated 01 Apr 2013
02/13 dated 01 Apr 2013
01/14 dated 01 Apr 2014
01/15 dated 11 June 2015
02/15 dated 11 June 2015
03/15 dated 11 June 2015