

Phone: 673-2331730 Fax : 673-2331730 AFTN: WBSBYNYX Email : ais.brunei@civil-aviation.gov.bn	NEGARA BRUNEI DARUSSALAM AERONAUTICAL INFORMATION SERVICE DEPARTMENT OF CIVIL AVIATION BRUNEI INTERNATIONAL AIRPORT, BB2513	NOTAM SUMMARY 03/2016 01 MARCH 2016
---	--	--

THE FOLLOWING NOTAM A/B SERIES WERE STILL IN FORCE AS OF 1603010001UTC. NOTAM NOT INCLUDED HAVE EITHER BEEN CANCELLED, TIME EXPIRED, SUPERSEDED BY AIP SUPPLEMENT OR INCORPORATED IN AIP.

LOCATION: BRUNEI (WBSB)		
NTM NR	DATE	TEXT
A/B0468	121113	EFF 1211150000/PERM Brunei Darussalam will only accept submission of FPL & ATS messages in new format filed in accordance with amendment 1 to the 15 th edition of PANS-ATM DOC 4444. FPL & ATS messages in present format will be rejected & as a consequence such flights will be delayed.
A/B0273	130910	EFF 1309102300/PERM All aircraft are advised to use new lead-in line for Stand 8.
A/B0279	130914	EFF 1309172300/PERM All aircraft are to used new lead-in line for Stand 5, 6 and 7.
A/B0296	130928	EFF 1309282200/PERM All aircraft advised to use new lead-in line for Stand 2.
A/B0387	131115	EFF 1311150615/PERM Stand 1 concourse and aerobridge is serviceable.
A/B0252	140726	EFF 1407260100/PERM All aircraft are advised to use new lead-in line for Stand 1.
A/B0535	151231	Effective 1512310345/1610312359 Presence of mobile crane, height 50m AMSL, within radius of 100m erected at 045817N 1145553E (Berakas Power Station, Kg Terunjing Baru). Remark/Crane marked with red and white chequered flag and lit at night.
A/B0034	160130	Effective 1601300500/1603310900 ILS LLZ rwy 03 'BE' frequency 108.9Mhz no standby facilities.
A/B0053	160203	Effective 1602130755/1605312359 RVR unserviceable.
A/B0072	160229	Effective 1602291600/1603302300 dly btn 1600/2300 repainting works on apron during no traffic movement. Work in progress will be cleared off during emergency cases.
A/B0073	160229	EFF 1602290950/1603310950 NDB "BR" freq 318Khz is not available due to installation of new equipment.
A/B0075	160229	Effective 1602291120/1603312359 Aerodrome Fire fighting downgrade to Category 8.
A/B0079	160301	Effective 1603020200/1603020600 Northern Parallel Tey temporary closed.

LOCATION: BRUNEI (WBSB)		NAVIGATIONAL WARNING
NTM NR	DATE	TEXT
A/B0006	160106	Between 0001/0430, 0600/0900 and 1100/1559 on 02,03, 17, 18, 22, 23 and 24 March 2016, Live firing exercise will take place at WBD509 (Binturan Range) Rmk/Illuminants will be used during night activity. Alt: AGL/12,000ft.
A/B0062	160229	Between 0001/0430, 0600/0900 and 1100/1559 on 08 and 09 March 2016, Live firing exercise will take place at WBD509 (Binturan Range) Rmk/Illuminants will be used during night activity. Alt: AGL/12,000ft.

LOCATION: ANDUKI (WBAK)		
NTM NR	DATE	TEXT
A/B0284	140901	Effective 1409010700/PERM The remote switch function for Aerodrome Ground Lighting (AGL) on freq 122.1Mhz is currently out of service due to installation of the new switchboard panel.
A/B0489	151201	Effective 151201000/1605312359 Brunei Shell Petroleum Headquarters Helipad position 043630.296N 1141717.238E to exercise caution for pilot landing at night will be at own discretion due to limited lights at helipad.
A/B0030	160129	Effective 1512100001/1603312359 Kuala Belait helipad windsock lightings (043523.40N 1141106.043E) unserviceable.
A/B0041	160202	Effective 1602020030/1606302359 Presence of an offshore rig "West Castor" height 202ft , position 045903.086N 1140842.943E at Fairley-2B.
A/B0050	160211	Effective 1602110600/1603312359 Rig Noble Same Hartley with Derrick height of 280ft ASL position 0521.618N 11438.577E. Pilot to exer caution.
A/B0052	160213	Effective 1601220001/1605012359 Presence of an offshore barge "Skd-Pelaut" with crane height of 200ft. Position at Champion West Area (CWDP-01) 051712675N 114436479E. Lit at night.
A/B0063	160229	Effective 1602290100/1603311100 daily between 2300/1100 Presence of crane operations with height of 60ft AGL position at E-31, left base Rwy 05 near Anduki airfield (043815N 11422561E).
A/B0064	160229	Effective 16022902150001/1604302359 Sequence flashing approach light (SFL) runway 23 all unserviceable.
A/B0065	160229	Effective 1602290240/1604302359 Presence of an offshore Rig "Ensco 505" with derrick height of 314ft AMSL position 053225N 1142215E. Lit at night.
A/B0066	160229	Effective 1602290250/1604302359 Presence of yellow color weight with dimension about 24 ins by 24 ins within weight of 500lb loc at the side of Anduki Compass.
A/B0068	160229	Effective 1602290330/1604302359 Panaga Health Centre Helipad (PHC) position 043638.889N 1141804.931E closed.
A/B0069	160229	Effective 1603010001/1606302359 concentration of birds in the vicinity of the Runway and Aerodrome. Remark/Pilot to exercise caution during landing and take-off.
A/B0071	160229	Effective 1602290800/1603102359 Presence of crane operations for wireline activities (TWC/1223) near Anduki Airfield. Position at left base Rwy 05,E-31 (Well S-415) .Height : 60ft.
A/B0078	160301	Effective 1603010140/1606302359 Presence of offshore barge, Maersk Completer with deck height of 150ft, Derrick height 350ft at Danau (0450.69N 11433.64E). Lit at night.

LATEST AIP AMENDMENT ISSUED : 01/14 dated 12 Dec 2014

LATEST AIC ISSUED : 02/15 dated 07 Dec 2015

CURRENT AIP SUPPLEMENTS : 01/01 dated 20 Sept 2001
02/01 dated 01 Nov 2001
02/09 dated 25 July 2009
07/09 dated 01 Oct 2009
04/10 dated 14 Sept 2010
01/13 dated 01 Apr 2013
02/13 dated 01 Apr 2013
01/14 dated 01 Apr 2014
01/15 dated 11 June 2015
02/15 dated 11 June 2015
03/15 dated 11 June 2015
04/15 dated 13 July 2015