

http://www.dca.gov.bn
Tel : 2330142, 2332741
Fax : 2331706



جابتن قنربغن عوام

JABATAN PENERBANGAN AWAM
KEMENTERIAN PENGANGKUTAN
DAN INFOKOMUNIKASI

DEPARTMENT OF CIVIL AVIATION
MINISTRY OF TRANSPORT AND
INFOCOMMUNICATIONS
BRUNEI INTERNATIONAL AIRPORT
BANDAR SERI BEGAWAN BB2513
BRUNEI DARUSSALAM

Ref: DCA/GT/203/V261

Date: 18 Jamadilakhir 1447
09 December 2025

Hjh Rozanti Hj Md Rozisham

Manager Quality Assurance
Royal Brunei Airlines Sdn Bhd
Engineering Department
P.O Box 737
Bandar Seri Begawan BS8671
Negara Brunei Darussalam

Dear Madam,

**V8-DLC (MSN 34789) - REQUEST FOR APPROVAL OF
ALTERNATIVE METHOD OF COMPLIANCE TO FAA AD 2025-20-03**

Reference is made to letter from Royal Brunei Airlines ref: E60/22/25/RR dated 17 Jamadilakhir 1447 / 08 December 2025 with regards to the above subject.

RB has requested to Director of Civil Aviation for his consideration to approve FAA Form 8100-9 ref: BSH-RBA-25-0034 and BSH-RBA-25-0035 dated 5 December 2025 and 06 December 2025 respectively as an alternative means of compliance (AMOC) with paragraph (g) of FAA AD 2025-20-03. The request has been reviewed and found to be satisfactory.

Each FAA Form 8100-9 approves the corresponding repair instructions provided by Boeing and developed by Jamco to address corrosion issues found on several locations within the Jamco Lavatory. These repairs are approved as AMOC in accordance with paragraph (k)(3) of the FAA AD 2025-20-03.

Repair Instructions approved under FAA Form 8100-9 Ref: BSH-RBA-25-0034 dated 05 December 2025:

- 1) RSRP for lower beam corrosion – RBA (V8-DLC_ZA447_4F-1RC) JCR-0892 Rev A
- 2) RSRP for lower fitting corrosion – RBA (V8-DLC_ZA447_4F-1RC) JCR-0893 Rev A

Repair Instruction approved under FAA Form 8100-9 ref: BSH-RBA-25-0035 dated 06 December 2025:

- 3) RSRP for lower beam corrosion – RBA (V8-DLC_ZA447_4F-1LC) JCR-0897 Rev A
- 4) RSRP for lower fitting corrosion – RBA (V8-DLC_ZA447_4F-1LC) JCR-0898 Rev A

6

In exercise of his power conferred by Regulation 8(2) of the Civil Aviation Regulations (CAP 290), the Director of Civil Aviation hereby grants a concession to approve the above-mentioned FAA 8100-9 ref: BSH-RBA-25-0034 and BSH-RBA-25-0035 dated 05 December 2025 and 06 December 2025 respectively as AMOC with paragraph (g) of the FAA AD 2025-20-03 for RB aircraft, B787-8, V8-DLC, MSN: 34789.

This grant of concession is subject to the following conditions:

1. This concession is limited to RB Boeing 787-8 aircraft, registration V8-DLC, MSN 34789.
2. The reference of this DCA variation letter (DCA/GT/203/V261), must be quoted and retained in the Aircraft Log Book and records;
3. No other deviation outside of those permitted by the FAA Form 8100-9 (Statement of Compliance with Airworthiness Standards) ref: BSH-RBA-25-0034 dated 05 December 2025 and ref: BSH-RBA-25-0035 dated 06 December 2025 is permitted to support the AMOC to paragraph (g) of the FAA AD 2025-20-03 without agreement from both the FAA and the Brunei Department of Civil Aviation;
4. All provisions of FAA AD 2025-20-03 that are not specifically addressed in the above FAA Form 8100-9 remain applicable and must be complied with.

Pursuant to regulation 78(3) of the Civil Aviation Regulations (CAP 290), any breach of these conditions shall render this grant of concession invalid during the continuance of the breach.

For further clarification, the Brunei DCA Airworthiness Section can be contacted through the following email address: airworth.regulatory@dca.gov.bn

“Bersatu Bersama Berbangsa, Beragama dan Beraja”

Yours faithfully,


(MOHAMAD AZLAN BIN MOHAMMAD JUNAIDI)
Acting Director of Civil Aviation

cc: Deputy Director of Civil Aviation (Regulator)
Airworthiness Section