

http://www.dca.gov.bn
Tel : 2330142, 2332741
Fax : 2331706



جابتن قنربغن عوام

JABATAN PENERBANGAN AWAM
KEMENTERIAN PENGANGKUTAN
DAN INFOKOMUNIKASI

DEPARTMENT OF CIVIL AVIATION
MINISTRY OF TRANSPORT AND
INFOCOMMUNICATIONS
BRUNEI INTERNATIONAL AIRPORT
BANDAR SERI BEGAWAN BB2513
BRUNEI DARUSSALAM

Ref: DCA/GT/203/V265

Date: 20 Ramadhan 1447
10 March 2026

Royal Brunei Airlines Sdn Bhd
Engineering Department
P.O Box 737
Bandar Seri Begawan BS8671
Negara Brunei Darussalam
Attention to: Technical Services Manager

Dear Sir,

**APPROVAL OF VARIATION TO MODIFICATION NO. 787-25LM018 – INSTALLATION
OF CREW REST CURTAIN AT SEAT ROW 11AC ON BOEING 787-8 AIRCRAFT**

Reference is made to the application for a Design Change or Repair (AIR Form 10) ref: EOM-787-25-013 Rev 00 from Royal Brunei (RB) dated 07 March 2026 with regards to the installation and removal of an additional crew rest curtain at seat row 11AC across all Boeing 787-8 operated by Royal Brunei Airlines.

Following review of the submitted documentation, including the supporting design data and compliance statements, the Department has no objection to the proposed modification. The installation of the crew rest curtain at seat row 11AC shall follow the same design data and configuration previously approved for seat row 11HK and shall be carried out in accordance with Engineering Order No. EOM-787-25-013 and RB Installation Drawing Document No. 787-25-053.

Accordingly, in exercise of powers conferred by regulations 78(1) and 7(4) of the Civil Aviation Regulations (CAP290) respectively, the Director of Civil Aviation hereby gives approval to RB to vary the approved modification No, 787-LM018 Rev. 0 and allow the installation of the curtain at cabin crew rest area seat row 11AC across all Boeing 787-8 operated and owned by RB.

This variation is granted subject to the following conditions:

- a. This variation is only valid for RB's Boeing B787-8 aircraft fleet (V8-DLA MSN: 34785, V8-DLB MSN: 34786, V8-DLC MSN: 34789, V8-DLD MSN: 34788 and V8-DLE MSN: 34791)

- b. The reference of this DCA variation letter (DCA/GT/203/V265), must be quoted and retained in the Aircraft Log Book and records.

Pursuant to regulation 78(3) of the Civil Aviation Regulations (CAP290), any breach of these conditions shall render this variation invalid during the continuance of the breach.

Please be informed that the corresponding AIR Form 10 for modification no. EOM-787-25-013 Rev 00 approving the installation of the modification has been duly issued.

For further clarification, the Brunei DCA Airworthiness Section can be contacted through the following e-mail address: airworth.regulatory@dca.gov.bn

“Berpendidikan, Berkemahiran Tinggi, Berkualiti Ke Arah Ekonomi yang Dinamik dan Berdaya Tahan”

Sincerely,

(MOHAMAD AZLAN BIN MOHAMMAD JUNAIDI)
Acting Director of Civil Aviation

cc: Deputy Director of Civil Aviation (Regulator)
Airworthiness Section