

**NEGARA BRUNEI DARUSSALAM**

**AERONAUTICAL INFORMATION**

<b>AERODROME</b>		<b>PRE-FLIGHT INFORMATION BULLETIN</b>			
Briefing Id	B1900001	Date/Time	19OCT20 1214		
Period		20OCT20 0000 TO 20OCT20 2359			
Briefing includes <b>ASHTAM NOTAM</b>					
Subject		Purpose	+B +BO +NB +NBO +M +NM	Traffic	+I +IV
AERODROME	WBSB WBAK WBKK WBKL WBKS WBGB WBGJ WBGR WBSG WBKW WBMU WBGG WMKK WMKJ WAAA WIHH WADD WARR				

**AIS INFORMATION**

**WBSB (BRUNEI INTL)**

<b>AGA</b>	<b>B)</b> 2010191000 E) STAND 7 CLSD DUE TO WIP.	<b>C)</b> 2010200100	(B0782/20)
<b>AGA</b>	<b>B)</b> 2010100645 E) STOPBAR AT E1 IS UNDER ABNORMAL OPERATIONAL STATUS. ALL ACFT TO FOLLOW ATC INSTRUCTIONS.	<b>C)</b> 2010242359	(B0751/20)
<b>AGA</b>	<b>B)</b> 2010010000 D) OCT 01-02 05-09 12-16 19-23 26-30 1730-2359 OCT 03-04 10-11 17-18 24-25 31-NOV 01 0000-2359 E) ALL COMMERCIAL AND GA FLT INCLUDING TECH STOP TO AND FM BRUNEI ARE REQUIRED TO NOTIFY THE AIRPORT AUTHORITY AT LEAST THREE (3) HRS IN ADVANCE. DRG THESE PERIODS DO NOT NOMINATE WBSB AS ALTN AD.	<b>C)</b> 2011012359	(B0724/20)
<b>CNS</b>	<b>B)</b> 2009280625 E) ILS RWY 21 U/S	<b>C)</b> 2010280830	(B0713/20)
<b>NAV</b>	<b>B)</b> 2010201130 E) UAV ACT WILL TAKE PLACE WI RAD 100M CENTRED ON COORD:- A. 044850N1143851E (MASJID PENGIRAN ANAK HAJI MUHAMMAD ALAM,KG SENGKARAI,TUTONG) B. 044943N1144331E (MASJID AR-RAHIM,BUKIT PANGGAL,TUTONG) F) GND <b>G)</b> 400FT AGL	<b>C)</b> 2010201330	(A0766/20)
<b>NAV</b>	<b>B)</b> 2010160100 D) OCT 16 19 23 26 30 0100-0400 NOV 2 6 9 13 16 20 23 27 30 0100-0400 E) UAV ACT WILL TAKE PLACE CENTRED ON COORD 050029N1150353E (RUKUN AL YAQEEEN CONSTRUCTION SITE). F) GND <b>G)</b> 200FT AGL	<b>C)</b> 2011300400	(B0773/20)
<b>NAV</b>	<b>B)</b> 2010010100 D) OCT 1 - DEC 31 0100-0400 0600-0900 E) UAV ACT WILL TAKE PLACE WI RAD 3500M CENTRED ON COORD 050023N1150620E (PULAU MUARA BESAR) F) GND <b>G)</b> 300FT AGL	<b>C)</b> 2012310900	(B0652/20)

**WBAK ()**

<b>AGA</b>	<b>B)</b> 2010050100 E) BSP HQ HELIPAD COORD 043628N1141729E, CLSD DUE TO WIP HELIPAD RESURFACING.	<b>C)</b> 2011052359	(B0735/20)
<b>AGA</b>	<b>B)</b> 2009140000 E) ALL HELICOPTER LANDING AT BRUNEI SHELL PETROLEUM HEAD QUARTERS HELIPAD COORD 043630N1141717E AND KUALA BELAIT HELIPAD COORD 043523N1141106E SHALL BE AT PILOT OWN DISCRETION	<b>C)</b> PERM	(B0696/20)
<b>AGA</b>	<b>B)</b> 2006300900 E) BIRDS CONCENTRATION IN THE VICINITY OF THE RWY AND AD. PILOT TO EXER CTN DRG LDG AND TKOF.	<b>C)</b> 2012312359	(B0471/20)
<b>OTH</b>	<b>B)</b> 2010190300 D) H24 E) PRESENCE OF WIRELINE CRANE OPS WITH HGT 60FT AT G-28 (WELL S-322) PSN 043712N1142100E SOUTHWEST OF SCOT. LIT AT NIGHT. PILOTS TO EXER CTN.	<b>C)</b> 2010252359	(B0781/20)
<b>OTH</b>	<b>B)</b> 2010190001 D) H24 E) PRESENCE OF HOIST JO-3 WITH HGT 110FT AT F-27(WELL S-693) POSN EAST OF SERIA CRUDE OIL TERMINAL COORD 043728N1142106E. LIT AT NIGHT. PILOTS TO EXER CTN.	<b>C)</b> 2010222359	(B0779/20)



<b>OTH</b>	<b>B)</b> 2010080707 <b>E)</b> CRANE ERECTED AT 055915.03N 1160442.44E HGT 330FT AMSL	<b>C)</b> 2012080707	(D1078/20)
<b>OTH</b>	<b>B)</b> 2010010000 <b>E)</b> AIS NEW OFFICE WILL OPR AT THE FLW ADS: AERONAUTICAL INFORMATION SERVICES (AIS) CIVIL AVIATION AUTHORITY OF MALAYSIA AIR TRAFFIC CONTROL CENTRE, JALAN KEPAYAN, 88618 KOTA KINABALU,SABAH REF AIP GEN 3.1-1 PARA 3.1.1.4	<b>C)</b> PERM	(D0986/20)
<b>OTH</b>	<b>B)</b> 2009290428 <b>E)</b> FOUR TOWER CRANE ERECTED AT 055820.86N 1160330.82E. APPROX 2750M BFR THR RWY20,600M W OF EXTENDED RCL.CRANES HGT/315FT AMSL	<b>C)</b> 2012312359 EST	(D1028/20)
<b>OTH</b>	<b>B)</b> 2009290333 <b>E)</b> TWO TOWER CRANE ERECTED AT 055821.02N 1160404.25E,APPROX 3100M NORTH OF RWY20.CRANE HGT/240FT AMSL	<b>C)</b> 2012312359 EST	(D1023/20)
<b>OTH</b>	<b>B)</b> 2009290310 <b>E)</b> CRANE ERECTED AT COORD 055748.42N 1160411.41E (URBAN TRANSFORMATION CENTER BUILDING, KARAMUNSING) CRANE HGT/300FT AMSL.	<b>C)</b> 2012312359 EST	(D1022/20)
<b>OTH</b>	<b>B)</b> 2009290308 <b>E)</b> THREE TOWER CRANES ERECTED AT 055703N 1160338E (AEROPOD,TANJUNG ARU),APRX 385M E OF RCL.CRANES HGT/300FT AMSL	<b>C)</b> 2012312359 EST	(D1021/20)
<b>OTH</b>	<b>B)</b> 2007291008 <b>E)</b> 3 TOWER CRANE ERECTED IN THE VICINITY OF AD COORD 055445.9N 1160351E. HGT 96 METER (315FT AMSL) FLAGGED AND LGTD AT NGT. RMK: LOCATED APPROX 2400M EAST OF THR RWY 02	<b>C)</b> 2010312359 EST	(D0764/20)

#### WBKL (LABUAN)

<b>AGA</b>	<b>B)</b> 2010012200 <b>E)</b> AD OPS HR CHANGED TO 2200-1000	<b>C)</b> 2010311400	(D1019/20)
<b>AGA</b>	<b>B)</b> 2009302359 <b>E)</b> UNEVEN RWY SFC RMK: 1. RWY 32 FM THR MARKER TIL 457M 2. RWY 14 FM THR MARKER TIL 914M PILOT TO EXER CTN DRG TKOF AND LDG	<b>C)</b> 2012302359 EST	(D1029/20)
<b>AGA</b>	<b>B)</b> 2009280121 <b>E)</b> WIP NEAR TWY A. RMK/PILOT TO EXER CTN DRG TAX.	<b>C)</b> 2012262359	(D1006/20)
<b>AGA</b>	<b>B)</b> 2009170630 <b>E)</b> TWY B CLSD	<b>C)</b> 2012182359 EST	(D0944/20)

#### WBKS (SANDAKAN)

<b>AGA</b>	<b>B)</b> 2010140600 <b>E)</b> GENERAL HELIPAD CLSD DUE TO WIP.	<b>C)</b> 2011141500	(D1083/20)
<b>AGA</b>	<b>B)</b> 2009120313 <b>E)</b> ACFT LDG RWY 26 SHALL MAKE 180 DEGREE TURN ON THE RWY.	<b>C)</b> 2011250000	(D0922/20)
<b>AGA</b>	<b>B)</b> 2009030730 <b>E)</b> TURNING PAD ON RWY 08 CLSD DUE WIP.	<b>C)</b> 2011251600 EST	(D0907/20)
<b>AGA</b>	<b>B)</b> 2009012300 <b>E)</b> AD OPS HR CHG TO 2300-1300	<b>C)</b> 2011301300	(D0850/20)

<b>AGA</b>	<b>B)</b> 2008251600 <b>E)</b> RWY08/26 DECLARED DIST CHANGED TO: RWY TORA(M) TODA(M) ASDA(M) LDA(M) RESA(M) 08 1923 1923 1923 NU 90X90 26 1923 1923 1923 1923 90X90 REF AIP SUPPLEMENT MALAYSIA 05/2020 DATED 28 MAY 2020 PAGE 3 ITEM NR 7	<b>C)</b> 2011251600	(D0843/20)
<b>AGA</b>	<b>B)</b> 2008251600 <b>E)</b> PAPI RWY 08 WITHDRAWN REF AIP SUPPLEMENT MALAYSIA 05/2020 DATED 28 MAY 2020 PAGE 3 ITEM NR 7	<b>C)</b> 2011251600	(D0844/20)
<b>AGA</b>	<b>B)</b> 2008251600 <b>E)</b> SALS RWY 08 WITHDRAWN REF AIP SUPPLEMENT MALAYSIA 05/2020 DATED 28 MAY 2020 PAGE 3 ITEM NR 7	<b>C)</b> 2011251600	(D0845/20)
<b>CNS</b>	<b>B)</b> 2009040646 <b>E)</b> GP/DME COORD TO READ AS 055404N 1180309E. REF TO AIP MALAYSIA AD 2-WBKS-1-6 PARA WBKS AD 2.19. AMD THE AFFECTED PAGE AND CHARTS ACCORDINGLY.	<b>C)</b> PERM	(D0904/20)
<b>CNS</b>	<b>B)</b> 2009040417 <b>E)</b> ILS/LOC ISKN COORD TO READ AS 055411N 1180418E REF TO AIP MALAYSIA AD 2-WBKS-1-6 PARA WBKS AD 2.19 AMD THE AFFECTED PAGE AND CHARTS ACCORDINGLY.	<b>C)</b> PERM	(D0902/20)
<b>CNS</b>	<b>B)</b> 2008251600 <b>E)</b> ILS/LOC RWY 08 ISKN FREQ 109.3MHZ WITHDRAWN REF AIP SUPPLEMENT MALAYSIA 05/2020 DATED 28 MAY 2020 PAGE 3 ITEM NR 7	<b>C)</b> 2011251600	(D0846/20)

#### WBGB (BINTULU)

<b>AGA</b>	<b>B)</b> 2010130636 <b>E)</b> AD OPS HR CHG TO 2200-1130	<b>C)</b> 2010221300	(D1091/20)
<b>AGA</b>	<b>B)</b> 2010060500 <b>E)</b> PAPI RWY 35 U/S	<b>C)</b> 2101072359	(D1051/20)

#### WBGJ (LIMBANG)

<b>AGA</b>	<b>B)</b> 2010052230 <b>E)</b> AD OPS HR CHG TO 2330-0900	<b>C)</b> 2010241030	(D1040/20)
------------	--	----------------------	------------

#### WBGR (MIRI)

<b>AGA</b>	<b>B)</b> 2010051135 <b>E)</b> VISUAL DOCKING GUIDANCE SYSTEM BAY 04 U/S RMK:PILOT TAX IN FLW MARSHALLER	<b>C)</b> 2011041600	(D1042/20)
<b>AGA</b>	<b>B)</b> 2008310128 <b>E)</b> TO ENABLE ATC TO APPLY MNM SPACING ON FNA THAT WILL ACHIEVE MAX RWY UTILISATION AND MINIMISE THE OCCURRENCE OF GO-AROUNDS. LDG ACFT SHALL EXIT THE LDG RWY WO DLA AT THE FIRST SUITABLE EXIT TWY OR AS INSTRUCTED BY ATC. ACFT LDG RWY 02 THAT IS UNABLE TO EXIT THE LDG RWY VIA AVBL EXIT TWY SHALL STOP AND REVERSE COURSE ON THE RWY ASAP. ACFT THAT NEED TO PROCEED TO THE END OF THE RWY AND REVERSE COURSE ON THE TURNING PAN SHALL INFORM ATC BFR LDG.	<b>C)</b> 2011302359 EST	(D0874/20)
<b>AGA</b>	<b>B)</b> 2007290247 <b>E)</b> AD OPS HR CHANGED TO 2200-1400	<b>C)</b> 2011121600	(D0761/20)
<b>CNS</b>	<b>B)</b> 2010070400 <b>E)</b> DVOR/DME VMI 112.4MHZ/CH71X U/S.	<b>C)</b> 2012312359	(D1062/20)
<b>OTH</b>	<b>B)</b> 2010051500	<b>C)</b> 2012312100 EST	(D1041/20)

D) 1500-2100  
 E) MOBILE CRANE OPERATING AT 042020.03N 1135937.05E - 042029.34N  
 1135934.17E CRANE HGT 150FT AGL (MIRI AIRPORT INTERCHANGE)

OTH B) 2010051500 C) 2012312100 (D1037/20)  
 D) DLY BTN 1500-2100  
 E) MOBILE CRANE OPERATING AT COORD 042024.12N 1135933.98E  
 WITHIN 1NM RADIUS AT HEIGHT 150FT.

OTH B) 2008111051 C) 2011112359 EST (D0814/20)  
 E) CRANE ERECTED 120FT AMSL AT 042026.56N 1135934.47E  
 760M FM THR RWY20.

**WBGs (SIBU)**

AGA B) 2010192200 C) 2010261400 (D1116/20)  
 E) AD OPS HR CHG AS FLW:  
 MON, TUE, WED, THU AND SAT 2200-1030  
 FRI AND SUN 2200-1230

**WBKW (TAWAU)**

ATM B) 2010120259 C) PERM (D1085/20)  
 E) CHG OF WPT RWY06 AND RWY24 COORD AS FLW :  
 RWY06 : 041825.28N 1180641.96E  
 RWY24 : 041911.11N 1180756.07E  
 REF TO AIP MALAYSIA AD2-WBKW-1-9,AD2-WBKW-8-9 AND AD2-WBKW-8-13,  
 AND THE AFFECTED PAGES ACCORDINGLY

**WBMU (MULU)**

AGA B) 2009270132 C) 2012272358 EST (D1004/20)  
 E) AD OPS HR CHANGE FM HJ TO 0000-0800.

AGA B) 2008310318 C) 2011302359 EST (D0876/20)  
 E) CRACK SFC ARE PRESENT ALONG THE TWY ON THE RIGHT AND LEFT SIDE.  
 RMK:1.PILOT TO EXER CTN DRG TAX IN/OUT.  
 2.AREA RIGHT AFT/BFR HLDG POINT OF ROUGHLY EST BTN 15M TO  
 35M AND NOT MARKED.

CNS B) 2008310320 C) 2011302359 EST (D0877/20)  
 E) DVOR VZU FREQ 112.8MHZ CH 75X U/S

**WBGg (KUCHING)**

AGA B) 2010130350 C) 2012130001 EST (D1090/20)  
 E) AFRS DOWNGRADED TO CAT 7

AGA B) 2010041700 C) 2010312000 (D1038/20)  
 D) 1700-2000  
 E) RWY 07/25 CLSD FOR MAINT

AGA B) 2009280517 C) 2012312359 EST (D1009/20)  
 E) SFC DEPRESSION ON TWY F

AGA B) 2009280516 C) 2012312359 EST (D1008/20)  
 E) ACFT UPON LDG RWY 25 AND VACATING VIA TWY A3 SHALL NOT MAKE A  
 RIGHT TURN ONTO TWY A AND PCD TO CARGO APN EXC FOR LGT ACFT.

AGA B) 2007300026 C) 2010311000 EST (D0766/20)  
 E) TWY A1 CLSD

CNS B) 2009280448 C) 2012280800 EST (D1007/20)  
 D) DLY 0000-0800  
 E) COMMISSIONING OF NEW KUCHING AREA CTL (SECT 2) RDO FREQ(S):  
 1.132.35 MHZ (PRI)  
 2.133.95 MHZ (SRY)  
 RMK: ACTIVATION OF THE FREQ IS SUBJ TFC COND AND ATC STAFF

AVAILABILITY.

<b>CNS</b>	<b>B)</b> 2008311525 <b>E)</b> ATS UNDER KUCHING AREA CTL (SECT 2) WITH RADIO FREQ(S) 132.35 MHZ (PRI) AND 133.95 MHZ (SRY) TEMP WITHDRAWN.	<b>C)</b> 2011302359 EST	(D0882/20)
<b>OTH</b>	<b>B)</b> 2010201030 <b>E)</b> OBST LIGHT WITHDRAWAL PHASE 1 CHIMNEY 410FT AT COORDS 013816N 1102754E (SEJINGKAT POWER CORPORATION PTE LTD)	<b>C)</b> 2011302300	(D1110/20)
<b>OTH</b>	<b>B)</b> 2009281340 <b>E)</b> CRANES ERECTED WI 400M RADIUS CENTRED ON 013421N 1102226E (LOT 2273 AND 2325 PLOT 1,SECTION 66,KUCHING CENTRAL LAND DISTRICT,KUCHING).CRANE HGT/200FT AMSL	<b>C)</b> 2011302359 EST	(D1016/20)
<b>OTH</b>	<b>B)</b> 2009180100 <b>E)</b> CONSTRUCTION CRANE ERECTED UP TO 63.0M AMSL(206.7 FT) AT COORD 012736.21N 1102543.03E,4.13NM ON BEARING 119 FM THR RWY25 RMK:TOWER CRANE WITH BOOM PAINTED YELLOW AND LIGHTED AT NIGHT	<b>C)</b> 2012182359 EST	(D0942/20)
<b>OTH</b>	<b>B)</b> 2008310130 <b>E)</b> PRESENCE OF CONSTRUCTION CRANE HGT 265FT AMSL AT COORD 013058N 1102044E (BEARING 005 DEG 5.5 KM FM KUCHING ARP 012907N 1102042E) RMK: (1) CONSTRUCTION CRANE PAINTED YELLOW AND LGTD (2) TWO BUILDING BLOCKS HEIGHT 240 FT AMSL (72.4M AMSL) UNDER CONSTRUCTION.	<b>C)</b> 2011302359 EST	(D0873/20)
<b>OTH</b>	<b>B)</b> 2007300835 <b>E)</b> TWO(2) TOWER CRANES ERECTED 43M AMSL AT 013028.05N 1102249.69E (RIVERDALE RESIDENCES,KUCHING) 2,070M ON BRG 040 FM THR RWY 25. RMK/TOWER CRANES WITH BOOM PAINTED AND LGTD AT NGT. <b>F)</b> GND <b>G)</b> 150FT AMSL	<b>C)</b> 2010302359 EST	(D0769/20)

**WMKK (KUALA LUMPUR/SEPANG INTL)**

<b>AGA</b>	<b>B)</b> 2010190130 <b>D)</b> OCT 19 0130-0230 21-23 1609-2200 24-25 0100-1100 <b>E)</b> 26 0130-0230 1600-2200 27-30 1600-2200 AND OCT 31-NOV 01 0100-1100 RWY 14L/32R CLSD	<b>C)</b> 2011011100	(A3806/20)
<b>AGA</b>	<b>B)</b> 2010180300 <b>E)</b> PORTION OF TWY B BTN B11 TIL INT B13 CLSD.	<b>C)</b> 2010210400	(A3892/20)
<b>AGA</b>	<b>B)</b> 2010160400 <b>E)</b> TWY H BTN TXL S3 AND TWY B CLSD	<b>C)</b> 2010210400	(A3856/20)
<b>AGA</b>	<b>B)</b> 2010151500 <b>D)</b> 15 1500-2200 19 0430-1200 20-22 1500-2200 <b>E)</b> 26 0430-1200 AND 27-29 1500-2200 RWY 15/33 CLSD	<b>C)</b> 2010292200	(A3807/20)
<b>AGA</b>	<b>B)</b> 2010151354 <b>E)</b> PAPI RIGHT HAND SIDE RWY 32L U/S.	<b>C)</b> 2010312200	(A3857/20)
<b>AGA</b>	<b>B)</b> 2010150948 <b>E)</b> CL LGT OF TWY U4 BTN TWY Q AND ACFT STAND P1 AND BTN ACFT STAND Q11 AND TWY Z WITHDRAWN.	<b>C)</b> 2010312200	(A3851/20)
<b>AGA</b>	<b>B)</b> 2010150945 <b>E)</b> TWY U3 CL LGT WITHDRAWN.	<b>C)</b> 2010312200	(A3850/20)
<b>AGA</b>	<b>B)</b> 2010150200	<b>C)</b> 2010301100	(A3808/20)

D) DLY 0200-1100 EXC 18 19 24-26 29  
E) RWY 14R/32L CLSD

AGA	B) 2010150200 E) TWY U3 ABM ACFT STAND J20 CLSD	C) 2011041100	(A3820/20)
AGA	B) 2010140708 E) PORTION OF TWY U4 FM ABM ACFT STAND P1 TIL P3 CLSD	C) 2010240200	(A3815/20)
AGA	B) 2010140701 E) PORTION OF TWY U3 FM ABM ACFT STAND J22 TIL TWY Q CLSD	C) 2010300200	(A3814/20)
AGA	B) 2010110800 E) TWY P CL LGT WITHDRAWN	C) 2010312200	(A3773/20)
AGA	B) 2010071004 E) RWY 15/33 CL LGTS U/S	C) 2010302200	(A3721/20)
AGA	B) 2010070436 E) APCH AND RWY LIGHTINGS RWY 14L/32R, RWY 14R/32L DOWNGRADE TO CAT I	C) 2010312200	(A3705/20)
AGA	B) 2009300415 E) STOPBAR LGT INT C1 TIL INT C11 WITHDRAWN. RMK: 1. LEAD IN/OUT LGT INT C1 TIL INT C11 NOT AVBL	C) 2010312200	(A3606/20)
CNS	B) 2007310803 E) SMR U/S RMK: DEP AND ARR SUBJ DLA	C) 2010302359 EST	(A2794/20)
ATM	B) 2009180129 E) IMPLEMENTATION OF RNAV (GNSS) SIMULTANEOUS INDEPENDENT PARALLEL APCH AT WMKK FOR THE FOLLOWING INSTRUMENT APPROACH PROCEDURES: RWY 14L RNAV (GNSS) RWY 14R RNAV Z (GNSS) RWY 14R RNAV Y (GNSS) RWY 15 RNAV (GNSS) RWY 32L RNAV Z (GNSS) RWY 32L RNAV Y (GNSS) RWY 32R RNAV (GNSS) RWY 33 RNAV (GNSS) RMK: 1 PILOTS SHALL MONITOR WMKK CATIS (ARRIVAL) FOR THE EXPECTED INSTRUMENT APPROACH. 2 OPERATORS ARE RESPONSIBLE TO OBTAIN THE GNSS RAIM PREDICTION ASSOCIATED WITH GNSS AVAILABILITY OR IT'S UNAVAILABILITY, AT THIS STAGE CAAM WOULD NOT PROVIDE THIS SERVICE. 3 PILOTS SHOULD NOTIFY ATC DEGRADATION OF THE RAIM DATA SIGNAL OR BEING UNABLE TO PERFORM THE RNAV (GNSS) APCH.	C) 2012182359 EST	(A3438/20)
ATM	B) 2008010530 E) REF TO AIP MALAYSIA AD2-WMKK-1-29 PARA 2.22.7 - VIS COND IS TEMPO SUSPENDED	C) 2010312300	(A2807/20)
OTH	B) 2010150939 E) INFO SIGN TWY P AND Q WITHDRAWN .	C) 2010312200	(A3849/20)
OTH	B) 2009290625 D) DLY 0000 - 1400 E) THREE CRANES ERECTED AT COORD OF 24410.9N 1014102.1E (ACFT STAND Q16). RMK:CRANES MAX HGT 30M.	C) 2011181400	(A3584/20)
OTH	B) 2008100418 E) CTL TOWER WEST (024445.7N1014105.0E) OBSTRUCTION LGT U/S RMK: PILOT TO EXER CTN	C) 2011102359 EST	(A2912/20)

**WMKJ (JOHOR BAHRU/SENAI INTL)**

AGA	B) 2010090001	C) 2010251400	(A3726/20)
-----	---------------	---------------	------------



E) APN BAY 3 CLSD FOR WIP  
RMK : MARKER BOARD AND BARRICADE PLACED TO DENOTE CLOSURE.

AGA	B) 2010030424 E) AD OPS HR CHANGED TO MON - THU 2000-1400 FRI - SUN 2300-1400	C) 2010252359	(A3658/20)
AGA	B) 2008141601 E) BAY 2A,3A,4A,5,6 AND 7 NOT AVBL	C) 2011141600	(A2990/20)
CNS	B) 2009291211 E) VMR FREQ 116.8 MHZ CH115X U/S	C) 2012292359	(A3598/20)
CNS	B) 2009291143 E) NDB JR FREQ 245KHZ U/S	C) 2012292359	(A3595/20)
CNS	B) 2009160633 E) ILS GP FREQ 333.8MHZ U/S	C) 2010311600 EST	(A3411/20)
CNS	B) 2008310000 E) OPS HR OF RADAR SVC CHG TO 0000-1200	C) 2011301200	(A3198/20)

**WAAA (MAKASSAR/SULTAN HASANUDDIN)**

AGA	B) 2010041000 E) PARKING STAND NR R18 AND R19 CLSD DUE TO WIP RMK :- TAXILINE BEHIND PARKING STAND R18 AND R19 NOV AVBL - PARKING STAND R15, R16 AND R17 AVBL TAXIING VIA TWY I AND K1	C) 2010270900	(A2253/20)
AGA	B) 2010010412 E) TWY CLSD DUE TO WIP AS FLW: - TWY H - TWY WP BTN TWY G AND TWY H RMK: HEAVY EQUIPMENT PRESENT	C) 2012311300	(A2237/20)
AGA	B) 2010010106 E) PARKING STAND B10, B11, B12, B13, B14, B15 CLSD DUE TO WIP	C) 2012292359	(A2230/20)
AGA	B) 2009291223 E) TO AVOID THE SPREAD OF COVID-19, OPERATION HOURS OF AD CHANGED TO 2000-1300 RMK: - EXC FOR MEDIVAC FLT, EMERGENCY FLT, TECH LDG, MILITARY FLT AND STATE FLT - AVBL FOR ENROUTE ALTN AD	C) 2010312359	(A2205/20)
AGA	B) 2009151200 E) SEQUENCE FLASHING LGT RWY 13 U/S DUE TO MAINT	C) 2012132359	(A2094/20)
AGA	B) 2008250310 E) PARKING STAND B31 UNTIL B37 CLSD RMK : TEMPORARY TAXILANE (LIMA ONE) L1 AVBL	C) 2011232359	(A1855/20)
AGA	B) 2008111533 E) PARKING STAND B24,B25,B26,B27,B28,B29,B41,B42,B43,B44,B45 AND B46 CLSD RMK: TEMPORARY TAXILANE (KILO ONE) K1 AVBL FOR SOUTH APRON	C) 2010291559	(A1757/20)
AGA	B) 2008111530 E) TEMPORARY TAXILANE LIMA ONE (L1), TAXILANE KILO ONE (K1) TAXILANE LIMA TANGO (LT) AND TAXILANE KILO TANGO (KT) AVAILABLE FOR SOUTH APRON RMK : ALL WIDE BODY ACFT FROM/TO PARKING STAND B10 AND B11 THROUGH TWY E AND USING TAXILANE L1	C) 2010291559	(A1756/20)
CNS	B) 1912060409 E) NEW SECONDARY FREQ OF MAKASSAR RADAR ON 123.80 MHZ REF AIP VOL I AMDT 83 DATED 05 DEC 19 ENR 2.1	C) PERM	(A4522/19)

**WIHH (JAKARTA/HALIM PERDANAKUSUMA)**

<b>AGA</b>	<b>B) 2010161600</b> <b>D) DAILY 1600-2100</b> <b>E) RWY 06/24 CLSD DUE TO WIP</b>	<b>C) 2011042100</b>	(A2365/20)
<b>AGA</b>	<b>B) 2010050600</b> <b>E) RWY 06/24 LIMITED TO ACFT WITH MAX MTOW 80.000KG</b>	<b>C) 2012310559</b>	(A2257/20)

**WADD (BALI INTL)**

<b>AGA</b>	<b>B) 2010090400</b> <b>D) OCT 09 0400-1800 OCT 10-DEC 30 0000-1800</b> <b>E) ALL TFC CTN ADZ DUE TO WIP PSN ON AREA WI COORD AS FLW:</b> 084445.60S1150930.06E-084447.87S1150930.15E- 084448.75S1150907.61E-084446.47S1150907.52E- 084445.60S1150930.06E RMK :-HVY EQPT PRESENT -CRANE ERECTED HGT 100FT	<b>C) 2012301800</b>	(A2301/20)
<b>AGA</b>	<b>B) 2009091600</b> <b>D) 09 1600-2300, SEP 10-OCT 30 1500-2300</b> <b>E) RWY 09/27 CLSD DUE TO WIP</b> RMK: EXC FOR EMERG LDG	<b>C) 2010302300</b>	(A2036/20)
<b>ATM</b>	<b>B) 2008051024</b> <b>E) ADDITIONAL DATA RELATED TO ATS COMMUNICATION FACILITIES AS FLW:</b> BALI DIRECTOR SECONDARY FREQ : 123.15MHZ REF AIP VOL II AMDT 90 DATED 23 APR 20 SUBSECTION WADD AD 2.18	<b>C) PERM</b>	(A1682/20)
<b>OTH</b>	<b>B) 2010080000</b> <b>E) TRIGGER NOTAM-PERM AIRAC AIP AMDT 95 WEF 08 OCT 2020</b> ESTABLISHMENT AND REVISION OF INFORMATION AT I GUSTI NGURAH RAI INTERNATIONAL AIRPORT BALI	<b>C) 2010212359</b>	(A1975/20)
<b>OTH</b>	<b>B) 2009280922</b> <b>E) OBSTACLE ANEMOMETER AWOS MIDDLE ERECTED ELEV 45.9FT HGT 32.8FT</b> PSN ON COORD 084457.48S1151024.24E	<b>C) 2012260900</b>	(A2196/20)

**WARR (SURABAYA/JUANDA)**

<b>AGA</b>	<b>B) 2010020221</b> <b>E) RWY HOLDING POSITION TWY N1 REPLACE TO TWY NP2 BTN TWY N2 AND TWY</b>  N9 DUE TO BUMPY SURFACE RMK: ALL TFC SUBJ ATC CLR	<b>C) 2012180200</b>	(A2248/20)
<b>AGA</b>	<b>B) 2009300428</b> <b>E) PARKING STAND A5 AND A6 CLSD DUE TO WIP</b> RMK: TAXILANE BEHIND PARKING STAND A5 AND A6 CLSD	<b>C) 2011231700</b>	(A2217/20)
<b>AGA</b>	<b>B) 2008310230</b> <b>E) ALL ACFT ARE NOT ALLOWED MAKE ONE WHEEL LOCK TURN ON RWY 10/28</b>	<b>C) 2011300159</b>	(A1907/20)
<b>AGA</b>	<b>B) 2007221400</b> <b>D) DAILY 1400-2159</b> <b>E) AD CLSD DUE TO WIP EXC FOR MEDIVAC HELICOPTER</b>	<b>C) 2010212159</b>	(A1570/20)
<b>CNS</b>	<b>B) 2009280405</b> <b>E) ATS COMMUNICATION CHANGED DUE TO SIGNIFICANT REDUCING TRAFFIC</b> SERVICE DESIGNATION : APP (SURABAYA EAST TMA, SURABAYA DIRECTOR AND SURABAYA WEST TMA (COMBINE SECTOR) CALLSIGN : SURABAYA WEST CONTROL FREQ : 125.1MHZ REF AIRAC AIP AMDT 86 DATED 30 JAN 20 SUBSECTION AD 2.18)	<b>C) 2010312359</b>	(A2190/20)

