NEGARA BRUNEI DARUSSALAM

AIP SUPPLEMENT

TEL : 673-2331730 AFS : WBSBYNYX FAX : 673-2331706 673-2331730 E-mail:<u>ais.brunei@dca.gov.bn</u> Website: <u>www.dca.gov.bn</u>

AERONAUTICAL INFORMATION SERVICE DEPARTMENT OF CIVIL AVIATION MINISTRY OF TRANSPORT AND INFOCOMMUNICATIONS BRUNEI INTERNATIONAL AIRPORT, BB2513

03 - 08/24 05 MAR

NR 03 - ANDUKI – HELIPAD

WIE/PERM Brunei Shell Petroleum Fire Services are not required to standby for any Military Helicopters unless requested at Kuala Belait Helipad and Brunei Shell Petroleum Head Office Helipad. Landing at Kuala Belait Helipad at night shall at the discretion of Pilot in command. Landing at Head Office Helipad is restricted to daylight hours only due to no availability of lightings.

NR 04 - BRUNEI – OBSTRUCTION LIGHT

EFF 2311060737/2404302359 Obstruction light on high pressure refining column with coordinate 044025N 1142825E (Brunei Liquefied Natural Gas, Lumut). Remark/ Pilot to exercise caution . Obstruction light height is 184ft above ground level.

NR 05 - ANDUKI – NAVIGATION AID

EFF 2312310300/2406302359 APAPI Runway 23 and Runway 05 unserviceavbl.

NR 06 - ANDUKI - TAXIWAY MARKING AIDS

EFF 2312310300/2406302359 Presence of Yellow Colour weight with dimension of about 24'X24' with weight of 500 pounds located at the of entrance Taxiway Charlie.

NR 07 - ANDUKI – BIRDS CONCENTRATION

EFF 2312310300/2406302359 Birds concentration in the vicinity of the runway and aerodrome. Pilot to exercise caution during landing and takeoff.

NR 08 - ANDUKI - RUNWAY MARKING

EFF 2312310300/2406302359 White colour markers denoting every 100M at the side of runway.

Mohamad Azlan Bin Mohammad Junaidi Acting Director of Civil Aviation Department of Civil Aviation Brunei Darussalam