

Phone: 673-2331730 Fax : 673-2331730 AFTN: WBSBYNYX Email : ais.brunei@civil-aviation.gov.bn	NEGARA BRUNEI DARUSSALAM AERONAUTICAL INFORMATION SERVICE DEPARTMENT OF CIVIL AVIATION BRUNEI INTERNATIONAL AIRPORT, BB2513	NOTAM SUMMARY 05/2015 02 MAY 2015
---	--	--

THE FOLLOWING NOTAM A/B SERIES WERE STILL IN FORCE AS OF 1505010001UTC. NOTAM NOT INCLUDED HAVE EITHER BEEN CANCELLED, TIME EXPIRED, SUPERSEDED BY AIP SUPPLEMENT OR INCORPORATED IN AIP.

LOCATION: BRUNEI (WBSB)		
NTM NR	DATE	TEXT
A/B0468	121113	Effective 1211150000/PERM Brunei Darussalam will only accept submission of FPL & ATS messages in new format filed in accordance with amendment 1 to the 15 th edition of PANS-ATM DOC 4444. FPL & ATS messages in present format will be rejected & as a consequence such flights will be delayed.
A/B0273	130910	Effective 1309102300/PERM All aircraft are advised to use new lead-in line for Stand 8.
A/B0279	130914	Effective 1309172300/PERM All aircraft are to used new lead-in line for Stand 5, 6 and 7.
A/B0296	130928	Effective 1309282200/PERM All aircraft advised to use new lead-in line for Stand 2.
A/B0387	131115	Effective 1311150615/PERM Stand 1 concourse and aerobridge is serviceable.
A/B0252	140726	Effective 1407260100/PERM All aircraft are advised to use new lead-in line for Stand 1.
A/B0115	150319	Effective 1503181630/1505170001 daily between 1600/0001 Rubber deposit removal WIP on Runway 03/21 during no traffic movement. WIP will be cleared off during emergency cases.
A/B0116	150319	Effective 1503181000/1505171600 daily between 1000/1600 repainting work on Runway 03/21 during no traffic movement. WIP will be cleared off during emergency cases.
A/B0185	150430	Effective 1505021830/1505030001 Repairing work to the damage pipe on grass area btn Twy E4 and E5 aprx 75M fm Twy E4 edge.
A/B0186	150430	Effective 1505011830/15012300 Repair works in progress on Twy E5 and Rwy 03 area due to crack surfaces.

LOCATION: BRUNEI (WBSB)		NAVIGATIONAL WARNING
NTM NR	DATE	TEXT
A/B0157	150413	Between 0001/0400 and 0500/0900 On 05, 06, 07, 12, 13, 14, 19, 20, 21, 22, 25, 26, 27, 28, 29, 30 and 31 May 2015. Parachute Jumping Exercise will take place within radius centered 4,000M of 045048N 1144151E (Penanjong Football Field). Rmk/Jump subject to ATC clearance. Alt: AGL/10,000ft.
A/B0158	150413	Between 0001/0400 and 0500/0900 On 05, 06, 07, 12, 13, 14, 19, 20, 21, 22, 25, 26, 27, 28, 29, 30 and 31 May 2015. Parachute Jumping Exercise will take place within radius centered 4,000M of 045626.36N 114551512.05E (Infront of PATDU RBAF Building). Rmk/Jump subject to ATC clearance. Alt: AGL/10,000ft.
A/B0164	150416	Between 0000/0900 On 13 and 14 May 2015. Firing exercise will take place within WBD509A (Bukit Agok). Alt: AGL/10,000ft.
A/B0165	150416	Between 0000/0900 On 03 and 04 June 2015. Firing exercise will take place within WBD509A (Bukit Agok). Alt: AGL/10,000ft.
A/B0166	150416	i) Between 0001/0400, 0600/0900 and 1100/1559 On 01, 15, 22 and 29 May 2015 ii) Between 0001/0430, 0600/0900 and 1100/1559 On 11, 12, 13 14, 19, 20, 21, 25, 26, 27 and 28 May 2015 Firing exercise will take place within WBD509 (Binturan Range). Rmk/Illuminants will be used during night activities. Alt:AGL/12,000ft.
A/B0167	150416	i) Between 0001/0430, 0600/0900 and 1100/1559 On 08, 09, 10, 11, 14, 15, and 16 June 2015. ii) Between 0001/0400, 0600/0900 and 1100/1559 On 12 June 2015 iii) Between 0001/0600 On 22, 23, 24 and 25 June 2015 iv) Between 0001/0330 on 26 June 2015 Firing exercise will take place within WBD509 (Binturan Range). Rmk/Illuminants will be used during night activities. Alt: AGL/12,000ft.

LOCATION: ANDUKI (WBAK)		
NTM NR	DATE	TEXT
A/B0284	140901	Effective 1409010700/PERM The remote switch function for Aerodrome Ground Lighting (AGL) on freq 122.1Mhz is currently out of service due to installation of the new switchboard panel.
A/B0054	150211	Effective 1502112200/1505112359 Bird concentration in the vicinity of the runway. Remark/Pilot to exercise caution during landing and take-off.
A/B0155	150412	Effective 1504120001/1507122359 Presence of offshore barge "SKD-Pelaut" with crane height 200ft position at FADP-01 (045706.44N 1140619.59E). Lit at night.
A/B0160	150415	Effective 1504150030/1507312359 Presence of an offshore rig "West Castor" with height of 202ft position 045040.193N 1143323.45E at DAWJ (Danau Area).

LOCATION: ANDUKI (WBAK)

NTM NR	DATE	TEXT
A/B0176	150427	Effective 1504272300/1505041000 daily between 2300/1000utc Presence of crane operations with height 60ft, position on Final Approach Rwy 05 (F-32). Pilots to exer ctn.
A/B0177	150427	Effective 1504272300/1505041000 daily between 2300/1000utc Presence of crane operations with height 60ft, position on Final Approach Rwy 23 (E-38).
A/B0178	150427	Effective 1504272300/1505041000 daily between 2300/1000utc Presence of crane operations with height 60ft, near Panaga Health Centre (F-14).
A/B0180	150428	Effective 1504280001/1510312359 Panaga Health Centre Helipad position 043638.8N 1141804.9E closed.
A/B0182	150429	Effective 1504290100/1505151000 Be adz Kuala Belait Helipad windsock is not avbl And pilots are to exercise caution.
A/B0184	150429	Effective 1504282200/1505072359 presence of crane "CTU Darat" (TSW/11) height approximate 128ft (39M). Position 400M West of Scout Base (0437.05N 11426.6E) at E20. Lit at night. Pilot to exercise caution.

LATEST AIP AMENDMENT ISSUED : 01/14 dated 12 Dec 2014

LATEST AIC ISSUED : 01/14 dated 10 Nov 2014

CURRENT AIP SUPPLEMENTS :

- 01/01 dated 20 Sept 2001**
- 02/01 dated 01 Nov 2001**
- 02/09 dated 25 July 2009**
- 07/09 dated 01 Oct 2009**
- 04/10 dated 14 Sept 2010**
- 01/13 dated 01 Apr 2013**
- 02/13 dated 01 Apr 2013**
- 01/14 dated 01 Apr 2014**
- 02/14 dated 01 Apr 2014**