

|   |  |  |
|---|--|--|
| <b>Phone: 673-2331730</b><br><b>Fax : 673-2331730</b><br><b>AFTN: WBSBYNYX</b><br><b>Email : <a href="mailto:ais.brunei@civil-aviation.gov.bn">ais.brunei@civil-aviation.gov.bn</a></b> | <b>NEGARA BRUNEI DARUSSALAM</b><br><b>AERONAUTICAL INFORMATION SERVICE</b><br><b>DEPARTMENT OF CIVIL AVIATION</b><br><b>BRUNEI INTERNATIONAL AIRPORT, BB2513</b> | <b>NOTAM SUMMARY</b><br><b>10/2015</b><br><b>01 OCTOBER 2015</b> |
|---|--|--|

**THE FOLLOWING NOTAM A/B SERIES WERE STILL IN FORCE AS OF 151001001UTC. NOTAM NOT INCLUDED HAVE EITHER BEEN CANCELLED, TIME EXPIRED, SUPERSEDED BY AIP SUPPLEMENT OR INCORPORATED IN AIP.**

| <b>LOCATION: BRUNEI (WBSB)</b> |               |   |
|--------------------------------|---------------|---|
| <b>NTM NR</b>                  | <b>DATE</b>   | <b>TEXT</b>   |
| <b>A/B0468</b>                 | <b>121113</b> | Effective 1211150000/PERM Brunei Darussalam will only accept submission of FPL & ATS messages in new format filed in accordance with amendment 1 to the 15 <sup>th</sup> edition of PANS-ATM DOC 4444. FPL & ATS messages in present format will be rejected & as a consequence such flights will be delayed. |
| <b>A/B0273</b>                 | <b>130910</b> | Effective 1309102300/PERM All aircraft are advised to use new lead-in line for Stand 8.   |
| <b>A/B0279</b>                 | <b>130914</b> | Effective 1309172300/PERM All aircraft are to used new lead-in line for Stand 5, 6 and 7.   |
| <b>A/B0296</b>                 | <b>130928</b> | Effective 1309282200/PERM All aircraft advised to use new lead-in line for Stand 2.   |
| <b>A/B0387</b>                 | <b>131115</b> | Effective 1311150615/PERM Stand 1 concourse and aerobridge is serviceable.  |
| <b>A/B0252</b>                 | <b>140726</b> | Effective 1407260100/PERM All aircraft are advised to use new lead-in line for Stand 1.   |
| <b>A/B0359</b>                 | <b>150912</b> | Effective 1509120800/1510122359 RVR unserviceable.  |
| <b>A/B0364</b>                 | <b>150915</b> | Effective 1509150830/1510312359 Aderome Fire Fighting downgared to cat 8.   |
| <b>A/B0373</b>                 | <b>150923</b> | Effective 1509220730/1510062359 ILS/DME Runway 21 unserviceable.  |

| <b>LOCATION: ANDUKI (WBAK)</b> |               |  |
|--------------------------------|---------------|--|
| <b>NTM NR</b>                  | <b>DATE</b>   | <b>TEXT</b>  |
| <b>A/B0284</b>                 | <b>140901</b> | Effective 1409010700/PERM The remote switch function for Aerodrome Ground Lighting (AGL) on freq 122.1Mhz is currently out of service due to installation of the new switchboard panel.  |
| <b>A/B0180</b>                 | <b>150428</b> | Effective 1504280001/1510312359 Panaga Health Centre Helipad position 043638.8N 1141804.9E closed.   |
| <b>A/B0222</b>                 | <b>150521</b> | Effective 1505210800/1511301000 Presence of yellow color weight with dimension of about 24' X 24' with weight of 500lbs located at the side of entrance taxiway C.   |
| <b>A/B0280</b>                 | <b>150702</b> | Effective 1507012200/1510312359 Presence of offshore barge "Maersk Completer" with deck height of 150ft/47m, derrick height 324ft/99m at Iron Duke.  |
| <b>A/B0328</b>                 | <b>150814</b> | Effective 1508140400/1510011000 Brunei Shell Headquarter helipad position 043630.296N 1141717.238E closed due to work in progress.   |
| <b>A/B0344</b>                 | <b>150828</b> | EFF 1508280130/1511302359 Bird concentration in the vicinity of the runway. Remark/Pilot to exercise caution during landing and take-off.  |
| <b>A/B0345</b>                 | <b>150829</b> | Effective 1508290640/1512312359 Presence of an offshore rig "West Castor" with height of 202ft position 051036.934N 1141829.139E at OSWJ-02.   |
| <b>A/B0369</b>                 | <b>150923</b> | Effective 1509212225/1511302359 Presence of offshore barge "SKD Pelaut" with height 200ft position at IRON DUKE (05940.514N 1143755.3442E) Lighted at night.   |
| <b>A/B0378</b>                 | <b>150917</b> | Effective 1509170001/1510302359 Presence of land rig "Flux SRD1" height 120ft (34m) at G-15 (Well S-225) position 043625.93N 1141832.3E . Obstacle light unserviceable. Pilot to exercise caution.                             |
| <b>A/B0371</b>                 | <b>150922</b> | Effective 1509220001/1510041000 Presence of crane (CTU DARAT TSW/11) height approximate 128ft (39M) position S-458 F-20 (04615224N 114326885E) West of Area Football Field Seria. Lighted at night. Pilot to exercise caution. |

| LOCATION: BRUNEI (WBSB) |      | NAVIGATIONAL WARNING |
|-------------------------|------|----------------------|
| NTM NR                  | DATE | TEXT                 |

NIL INFORMATION

**LATEST AIP AMENDMENT ISSUED : 01/14 dated 12 Dec 2014**

**LATEST AIC ISSUED : 01/15 dated 11 June 2015**

**CURRENT AIP SUPPLEMENTS : 01/01 dated 20 Sept 2001**  
**02/01 dated 01 Nov 2001**  
**02/09 dated 25 July 2009**  
**07/09 dated 01 Oct 2009**  
**04/10 dated 14 Sept 2010**  
**01/13 dated 01 Apr 2013**  
**02/13 dated 01 Apr 2013**  
**01/14 dated 01 Apr 2014**  
**01/15 dated 11 June 2015**  
**02/15 dated 11 June 2015**  
**03/15 dated 11 June 2015**

-/hjh siti zaliha/October 2015