

# NEGARA BRUNEI DARUSSALAM

AIP  
SUPPLEMENT

TEL : 673-2331730  
AFS : WBSBYNYX  
FAX : 673-2331706  
673-2331730  
E-mail: [ais.brunei@civil-aviation.gov.bn](mailto:ais.brunei@civil-aviation.gov.bn)  
Website: [www.civil-aviation.gov.bn](http://www.civil-aviation.gov.bn)

AERONAUTICAL INFORMATION SERVICE  
DEPARTMENT OF CIVIL AVIATION  
MINISTRY OF TRANSPORT AND  
INFOCOMMUNICATIONS  
BRUNEI INTERNATIONAL AIRPORT, BB2513

11/19  
15<sup>th</sup> July

## UNSERVICEABILITY OF RUNWAY VISUAL RANGE BRUNEI INTERNATIONAL AIRPORT

### 1. INTRODUCTION

Runway Visual Range at Brunei International Airport unserviceable due to replacement with a new airport weather observation system.

### 2. PERIOD

From 0200UTC 03 July to 2359UTC 30 September 2019.

### 3. REMARKS

- i) Any changes to the contents of this page will be notified by NOTAM.
- ii) NOTAM A/B0482/19 dated 03 July 2019 is hereby superded

Haji Bujang Haji Tinkong  
Acting Director of Civil Aviation  
Department of Civil Aviation  
Brunei Darussalam